

Preventing failure of gearboxes – Food processing

- 5th September Gearbox removed from service & inspection revealed :
 - Oil pump failed (heavily damaged bearing & drive pin sheared).
 - Debris in gearbox but no gearbox damage.
- As a result, gearbox design changed to have external oil pump.
- Vibration Analysis showed no issues throughout.

